

BID NO. 7319

**Addition to Taftville Fire Station
Taftville Volunteer Fire Department**

ADDENDUM #2

The due date for this bid has been rescheduled. This bid will be due on Friday, February 17, 2012 at 2:00 PM.

Additional details pertaining to the site work will be issued in Addendum #3.

Bidders are advised that an oil/water separator will **not** be required for this project. See letter attached.

Overhead doors shall be from the Overhead Door Co., series 426 with an RSX trolley operator. The entry door will be a commercial grade type from Ceco, Republic, Security Metal Products or equal approved by the Purchaser.

Dumpster space will be available on site.

**William Block
City Purchasing Agent**

Bill Block

From: Joe East [jeast@cityofnorwich.org]
Sent: Friday, January 27, 2012 9:04 AM
To: timjencks@taftvillefire.org
Cc: Bill Block (E-mail)
Subject: oil separators

Tim,

As per the 2003 IPC portion of the 2005 Ct State Building Code there is no requirement for an oil separator for the floor drain in a storage garage where no maintenance, fueling, or washing occurs:

1003.4 Oil separators required.

At repair garages, carwashing facilities with engine or undercarriage cleaning capability and at factories where oily and flammable liquid wastes are produced, separators shall be installed into which all oil-bearing, grease-bearing or flammable wastes shall be discharged before emptying in the building drainage system or other point of disposal.

1003.4.2.2 Garages and service stations.

Where auto-mobiles are serviced, greased, repaired or washed or where gasoline is dispensed, oil separators shall have a minimum capacity of 6 cubic feet (0.168 m³) for the first 100 square feet (9.3 m²) of area to be drained, plus 1 cubic foot(0.28 m³) for each additional 100 square feet (9.3 m²) of area to be drained into the separator. Parking garages in which servicing, repairing or washing is not conducted, and in which gasoline is not dispensed, shall not require a separator. Areas of commercial garages utilized only for storage of automobiles are not required to be drained through a separator.

Please call with any questions

Respectfully,

Joe East, ABO